

QUALITY CONTROL PLAN - WORKS INST. FOR PROCESS INSTRUCTIONS

Customer : TOYOTA GB Plant : Customer Part Number : TYG-123 Customer Reference :	Customer Drawing Number : Customer Drawing Issue : Customised Number : Internal Reference : 00251-0277-004A	Material : steel Material Specification : EN223-Q1 Warrant/ISIR : ISIR999
Part Number : 00251-02077 Description : RX300 PLATE Plan Number : CP000007	Drawing Number : 00251-02077/2 Drawing Issue : 15/09/2005 - 2 Issue Number : 4	Engineer : A Black Supervisor : B Brown Latest Issue Date : 04/01/2005
Process No. 1	Process Name : Issue Material Process Description : Purchase and Issue Raw material	


Works Inst. : TESTINST
Description : Test work instruction
Aid Number : VA000001

Issue Number : 1

Latest Issue Date : 03/01/2005

Instructions

These are work instructions.
Wash, clean and dry the sample.
Measure overall length with vernier.



Works Inst. File : C:\qcwin2\Pictures\ex01.bmp